

APPENDIX A

PHOTOS



Picture #1: Roof construction system of the historic garage-Maintenance/Vehicle storage



Picture #2: Stud wall, ceiling joists and roof rafters of the historic garage-Maintenance/Vehicle storage. Deteriorations in siding is visible from inside



Picture #3: Headers over garage door openings and supporting 4x6 wood posts in the historic garage-Maintenance/Vehicle storage. No hurricane ties at ends of roof rafters.



Picture #4: Continuous 4x6 sill plate at perimeter of the historic garage-Maintenance/Vehicle storage. 1/2" diameter anchor is visible in the picture.



Picture #5: Crack in the concrete garage slab of the historic garage-Maintenance/Vehicle storage.



Picture #6: Deterioration of siding at the historic garage-Maintenance/Vehicle storage.



Picture #7: Damaged stone foundation on the south side of the historic barn.



Picture #8: Damaged stone foundation on the south side of the historic barn.



Picture #9: Damaged stone foundation on the south side of the historic barn. Super-Structure is on the verge of collapsing



Picture #10: Individual stone piers in the historic barn are in acceptable conditions.



Picture #11: Stone foundation at north side of the historic barn is in acceptable conditions.



Picture #12: Super-structure of the historic barn is on the verge of collapsing.



Picture #13: Roof construction system of the historic farm outbuilding



Picture #14: Historic farm outbuilding. No hurricane ties at rafter ends and no headers over openings



Picture #15: Major structural crack on the foundation wall of the historic farm outbuilding



Picture #16: Absence of downspouts in historic farm outbuilding.