

*TREES GREATER THAN OR EQUAL TO 75% OF THE COUNTY CHAMPION AS LISTED IN THE 2017-2018 REGISTER OF CHAMPION TREES, MONTGOMERY COUNTY, MD

| Mitigation Tree Schedule | | | | | |
|--------------------------|--------|------------------------------------|----------------|-----------------------------|--|
| Quantity | Symbol | Botanical name/ Common Name | Size (Caliper) | Total Caliper Inches | |
| 12 | FGR | Fagus grandifolia | 3.0" | 36" | |
| | | American Beech | | | |
| 14 | LTU | Liriodendron tulipfera | 3.0" | 42" | |
| | | Tulip poplar | | | |
| 12 | QAL | Quercus alba | 3.0" | 36" | |
| | | White Oak | | | |
| 16 | QRU | Quercus rubra | 3.0" | 48" | |
| | | Red Oak | | | |
| | | | Total | 162" | |

NOTE: PLEASE SEE LANDSCAPE PLAN FOR FULL PLANT SCHEDULE

| Non-mitigation | ation Tree S | Schedule | |
|----------------|--------------|--|----------------|
| Quantity | Symbol | Botanical Name/Common Name | Size (Caliper) |
| Canopy Tr | ees | | |
| 5 | ARU | Acer rubrum/Red Maple | 2"-2 1/2" Cal. |
| 5 | BNI | Betula nigra/River Birch | 7'-8' Ht. |
| 5 | POC | Platanus occidentalis/Sycamore | 2"-2 1/2" Cal. |
| 2 | QRU | Quercus rubra/Red Oak | 2"-2 1/2" Cal. |
| Ornament | al Trees | | |
| 4 | AMA | Amelanchier arborea/Serviceberry | 6'-8' Ht. |
| 14 | DVI | Diospyros virginiana/Persimmon | 6'-8' Ht. |
| 10 | SAL | Sassafras albidum/Sassafras | 6'-8' Ht. |
| Evergreen | Trees | | |
| 7 | JVI | Juniperus virginiana/Eastern Red Cedar 6'-8' Ht. | |

INSPECTIONS

All field inspections must be requested by the applicant.

Field Inspections must be conducted as follows:

Plans without Planting Requirements

- 1. After the limits of disturbance have been staked and flagged, but before any clearing or
- 2. After necessary stress reduction measures have been completed and protection measures
- have been installed, but before any clearing and grading begin and before release of the

Signature:

REVIEW AND APPROVAL

Park Development

Central Maintenance

3. After completion of all construction activities, but before removal of tree protection fencing, to determine the level of compliance with the provision of the forest conservation.

Additional Requirements for Plans with Planting Requirements

- 4. Before the start of any required reforestation and afforestation planting.
- 5. After the required reforestation and afforestation planting has been completed to verify
- that the planting is acceptable and prior to the start the maintenance period. 6. At the end of the maintenance period to determine the level of compliance with the
- provisions of the planting plan, and if appropriate, release of the performance bond.

| DEVELOPER'S CERTIFICATE | | | | | |
|--|--|--|--|--|--|
| The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. <u>SC2019012</u> , including financial bonding, forest planting, maintenance, and all other applicable agreements. | | | | | |
| Developer's Name: M-NCPPC, PPD Printed Company Name | | | | | |
| Contact Person or Owner: MICHAEL ZELASKI, P.E. | | | | | |
| Printed <i>Name</i> | | | | | |
| Address: 2425 REEDIE DRIVE, II+h FLR. WHEATON, MD 20902 | | | | | |
| Phone and Email: 301.495.2465 | | | | | |
| Michael.Zelaski@montgomeryparks.org | | | | | |

Michael Zelaski

Date

Date

REVIEW AND APPROVAL

Superintendent of Parks

Park Police

Additional Trees to be Removed Tree number | Size DBH | Common name Condition Comments A 15 Pine Dead Dead will need to be removed for park user safety B 20 Ash Dead Dead will need to be removed for park user safety Dead will need to be removed for park user safety C 20 Tulip poplar Dead E 20 Ash Dead Dead will need to be removed for park user safety NA NA Dead will need to be removed for park user safety Dead NA Ash Dead Dead will need to be removed for park user safety H 6 Ash Dead Dead will need to be removed for park user safety 15 Oak Dead Dead will need to be removed for park user safety 12 Oak Dead Dead will need to be removed for park user safety K 20 Ash Dead Should be removed for park user safety 29 Korean pine Fair Should be removed for park user safety 8 24 Tulip poplar Good Should be removed for park user safety 15 26 Red maple Good Should be removed for park user safety 80 12 Oak Dead Dead will need to be removed for park user safety 24 | Swamp white oak | Good 106 Should be removed for park user safety 134 27 Red oak Dead will need to be removed for park user safety 136 26 Should be removed for park user safety Red maple Good 27 Good Should be removed for park user safety 137 |Tulip poplar Should be removed for park user safety 138 29 Tulip poplar Good 150 Should be removed for park user safety 26 |White oak Should be removed for park user safety 153 25 Tulip poplar Fair 156 27 White oak Dead will need to be removed for park user safety Poor 28 Red oak Good Should be removed for park user safety 28 Tulip poplar Good Should be removed for park user safety 209 24 |Tulip poplar Should be removed for park user safety Good 211 27 Should be removed for park user safety Green Ash Fair 254 27 Eastern red cedar Poor Dead will need to be removed for park user safety Should be removed for park user safety 26 |Tulip poplar 380 32 Sycamore Good Should be removed for park user safety 28 Dead will need to be removed for park user safety 381 Sycamore Dead R564 28 Good Should be removed for park user safety Green Ash R610 24 White Ash Dead will need to be removed for park user safety Poor R631 25 Black Walnut Fair Should be removed for park user safety

NOTE: TREES LESS THAN 24" DBH TO BE REMOVED ARE ONLY CALLED OUT WHEN LOCATED OUTSIDE OF LOD. ADDITIONAL TREES LESS THAN 24" DBH WITHIN LOD WILL BE REMOVED DURING CONSTRUCTION. CONTRACTOR IS RESPONSIBLE FOR VISITING THE SITE PRIOR TO CONSTRUCTION AND QUANTIFYING SMALLER TREE REMOVALS WITHIN LOD

Sequence of Events for Properties Required to Comply With Forest Conservation Plans, Exemptions from Submitting Forest Conservation Plans, and Tree Save Plans

The property owner is responsible for ensuring all tree protection measures are performed in accordance with the approved final forest conservation plan or tree save plan, and as modified in the field by a Planning Department Forest Conservation Inspector. The measures must meet or exceed the most recent standards published by the American National Standards Institute (ANSI

Pre-Construction

- 1. An on-site pre-construction meeting is required after the limits of disturbance have been staked and flagged and before any land disturbance.
- 2. The property owner must arrange for the meeting and following people should must participate at the pre-construction meeting: the property owner or their representative, construction superintendent, International Society of Arboriculture (ISA) certified arborist/Maryland Licensed Tree Expert (representing owner) that will implement the tree protection measures, The Planning Department Forest Conservation Inspector, and Montgomery County Department of Permitting Services (DPS) Sediment Control Inspector. The purpose of this meeting is verify the limits of disturbance and discuss specific tree protection and tree care measures shown on the approved plan. No land disturbance shall begin before tree protection and stress-reduction measures have been implemented and approved by the Planning Department's Forest Conservation Inspector.
 - a. Typical tree protection devices include: i. Chain link fence (four feet high)
 - ii. Super silt fence with wire strung between the support poles (minimum 4 feet high) with high visibility flagging.
 - iii. 14 gauge, 2 inch x 4 inch welded wire fencing supported by steel T-bar
 - posts (minimum 4 feet high) with high visibility flagging. b. Typical stress reduction measures may include, but are not limited to: i. Root pruning with a root cutter or vibratory plow designed for that
 - purpose. Trenchers are not allowed, unless approved by the Forest Conservation Inspector
 - ii. Crown Reduction or pruning
 - iii. Watering iv. Fertilizing
 - v. Vertical mulching

vi. Root aeration systems Measures not specified on the Forest Conservation Plan may be required as determined by the Forest Conservation Inspector in coordination with the property owner's arborist.

- 3. A Maryland Licensed Tree expert must perform, or directly supervise, the implementation of all stress reduction measures. Documentation of the process (including photographs) may be required by the Forest Conservation Inspector, and will be determined at the pre-construction meeting.
- 4. Temporary tree protection devices must be installed per the approved Forest Conservation Plan, Exemption Plan, or Tree Save Plan and prior to any land disturbance. The Forest Conservation Inspector, in coordination with the DPS Sediment Control Inspector, may make field adjustments to increase the survivability of trees and forest shown as saved on the approved plan.
- 5. Tree protection fencing must be installed and maintained by the property owner for the duration of construction project and must not be altered without prior approval from the Forest Conservation Inspector. All construction activity within protected tree and forest areas is prohibited. This includes the following activities:
- a. Parking or driving of equipment, machinery or vehicles of any type.
- b. Storage of any construction materials, equipment, stockpiling, fill, debris, etc.
- c. Dumping of any chemicals (i.e., paint thinner), mortar or concrete remainder, trash, garbage, or debris of any kind.
- d. Felling of trees into a protected area.
- e. Trenching or grading for utilities, irrigation, drainage, etc.
- 6. Forest and tree protection signs must be installed as required by the Forest Conservation Inspector. The signs must be waterproof and wording provided in both English and Spanish.

During Construction

- 7. Periodic inspections will be made by the Forest Conservation Inspector. Corrections and repairs to tree protection devices must be completed within the timeframe given by the Inspector.
- 8. The property owner must immediately notify the Forest Conservation Inspector of any damage to trees, forests, understory, ground cover, and any other undisturbed areas shown on the approved plan. Remedial actions, and the relative timeframes to restore these areas, will be determined by the Forest Conservation Inspector.

Post-Construction


- 9. After construction is completed, but before tree protection devices have been removed, the property owner must request a final inspection with the Forest Conservation Inspector. At the final inspection, the Forest Conservation Inspector may require
- additional corrective measures, which may include: a. Removal, and possible replacement, of dead, dying, or hazardous trees
- b. Pruning of dead or declining limbs
- c. Soil aeration d. Fertilization
- e. Watering

protection fencing is removed.

- f. Wound repair g. Clean up of retention areas, including trash removal
- 10. After the final inspection and completion of all corrective measures the Forest Conservation Inspector will request all temporary tree and forest protection devices be removed from the site. Removal of tree protection devices that also operate for erosion and sediment control must be coordinated with both DPS and the Forest Conservation Inspector and cannot be removed without permission of the Forest Conservation Inspector. No additional grading, sodding, or burial may take place after the tree
- 11. Long-term protection measures, including permanent signage, must be installed per the approved plan. Installation will occur at the appropriate time during the construction project. Refer to the approved plan drawing for the long-term protection measures to be

Tree Protection Fence Detail


Not to scale



NOTES

- 1. Practice may be combined with sediment control
- 2. Location and limits of fencing should be coordinated in field with arborist.
- Boundaries of protection area should be staked prior to installing protective device.
- Root damage should be avoided.
- Protection signage is required. Fencing shall be maintained throughout

Montgomery County Planning Department • Market Mr. McPPC MontgomeryPlanning.org



1. RETENTION AREAS WILL BE SET AS PART OF THE REVIEW PROCESS AND PRECONSTRUCTION 2. BOUNDARIES OF RETENTION AREAS MUST BE STAKED AT THE PRECONSTRUCTION MEETING

AND FLAGGED PRIOR TO TRENCHING. 3, EXACT LOCATION OF TRENCH SHALL BE DETERMINED IN THE FIELD IN COORDINATION WITH

4. TRENCH SHOULD BE IMMEDIATELY BACKFILLED WITH EXCAVATED SOIL OR OTHER ORGANIC SOIL AS SPECIFIED PER PLAN OR BY THE FC INSPECTOR.

5. ROOTS SHALL BE CLEANLY CUT USING VIBRATORY KNIFE OR OTHER ACCEPTABLE EQUIPMENT.

6. ALL PRUNING MUST BE EXECUTED WITH LOD SHOWN ON PLANS OR AS AUTHORIZED IN WRITING BY THE FC INSPECTOR.

ROOT PRUNING DETAIL

THE FOREST CONSERVATION (FC) INPECTOR.

"I, hereby certify that this Natural Resource Inventory is in accordance with the methodology described in the Trees Technical Manual; adopted by Montgomery County (July 1992), which was developed by the Natural Resources Division of the Maryland-National Capital Park and Planning Commission (1982)."

Signature: . Brian Morgan, P.L.A.

Columbia, MD 21044

Greenman-Pedersen, Inc. 11000 Broken Land Parkway, Sui

PROJECT

DATE: JANUARY 2021

North Branch Trail

FOREST CONSERVATION PLAN 13 TAX MAP GRID: HS21 & HS23 WSSC GRID: 220NW05, 221NW05

FCP-14

Date

Date

Date

The Maryland-National Capital Park and Planning Commission

Montgomery County Department of Park and Planning 2425 Reedie Drive, 11th Floor Wheaton, Maryland 20902 (301) 495-2535

REVISIONS Rev. No. Date Description

LANS ISSUED FOR:CONSTRUCTION DRAWINGS

Thereby certify that these documents were prepared or approved by me, and that lam a duly licensed landscape architect under the laws of the state of Maryland license No. 3487 Expiration Date: 07/03/22

Professional Certification:

MONTGOMERY COUNTY, MD SCALE: AS SHOWN

Date

www.gpinet.com

Checked By

Checked By

Checked By

Checked By:

GPI

Greenman-Pedersen, Inc.

Columbia, MD 21044

Tel: 410.880.3055

DESIGN

Landscape Architec

Architect

Drawn by

Engineering | Design | Planning | Construction Managemen

11000 Broken Land Parkway, Suite 500

| | | Tree number Size DBH Common name Scientific name Condition Comments | Tree number Size DBH Common name Scientific name Condition Comments | Tree number Size DBH Common name Scientific name Condition Comments |
|--|--|---|--|--|
| | | 89 30 Tulip poplar Liriodendron tulipifera Good 90 25 Tulip poplar Liriodendron tulipifera Good | 218 25 White oak Quercus alba Good 219 36 White oak Quercus alba Fair Broken branches in crown | 344 41 White oak Quercus alba Good 345 28 White oak Quercus alba Fair sparse canopy 346 31 White oak Quercus alba Fair sparse canopy, dead branches, white patch disease |
| | | 91 31 Red oak Quercus rubra Good 92 27 Tulip poplar Liriodendron tulipifera Good | 220 24 Green ash Fraxinus pennsylvanica Fair Dead branches, vines 221 33 Sycamore Platanus occidentalis Fair On streambank, roots exposed, lean 222 38 Tulip poplar Liriodendron tulipifera Fair Vines | 347 24 White oak Quercus alba Good 348 31 White oak Quercus alba Fair uneven canopy, broken branches |
| | | 93 24 Mockernut hickory Carya alba Excellent 94 26 Pignut hickory Carya glabra Excellent | 223 29 Tulip poplar <i>Liriodendron tulipifera</i> Poor Strong lean, moss covered | 349 30 White oak Quercus alba Fair choked by poison ivy 350 34 White oak Quercus alba Good |
| | | 95 25 White oak Quercus alba Fair Strong lean, uneven crown 96 25 Red oak Quercus rubra Good | 224 40 Sycamore Platanus occidentalis Fair Dead branches, vines 225 38 Tulip poplar Liriodendron tulipifera Fair Vines 226 32 Tulip poplar Liriodendron tulipifera Good | 351 50 Tulip poplar Liriodendron tulipifera Good 352 25 Tulip poplar Liriodendron tulipifera Good 353 25 Tulip poplar Liriodendron tulipifera Excellent |
| | | 97 29 Tulip poplar Liriodendron tulipifera Good 98 26 Pignut hickory Carya glabra Excellent | 227 25 White oak Quercus alba Good 228 31 White oak Quercus alba Fair Broken branches in crown, vines | 354 29 Tulip poplar Liriodendron tulipifera Excellent 355 38 Tulip poplar Liriodendron tulipifera Poor topped in storm, center trunk rot |
| | | 99 32 Red oak Quercus rubra Good 100 24 White oak Quercus alba Fair Strong lean, uneven crown | 229 27 Sycamore Platanus occidentalis Fair Stream bank, roots exposed 230 25 White oak Quercus alba Good | 356 26 Tulip poplar Liriodendron tulipifera Excellent 357 26 Tulip poplar Liriodendron tulipifera Good |
| | | 101 26 White oak Quercus alba Excellent 102 25 White oak Quercus alba Good | 230 25 Write Oak Quercus uibu Good 231 32 Red oak Quercus rubra Good 232 26 Tulip poplar Liriodendron tulipifera Good | 358 30 Tulip poplar Liriodendron tulipifera Good 359 30 Tulip poplar Liriodendron tulipifera Excellent 360 27 Tulip poplar Liriodendron tulipifera Good |
| | | 103 26 Tulip poplar Liriodendron tulipifera Good 104 25 White oak Quercus alba Excellent | 232 26 Tulip popial Einodentron talipijera Good 233 29 Tulip poplar Liriodendron tulipijera Good 234 32 Red oak Quercus rubra Good | 360 27 Tulip poplar Liriodendron tulipifera Good 361 28 Tulip poplar Liriodendron tulipifera Fair sparse canopy 362 26 Tulip poplar Liriodendron tulipifera Good |
| 1 28 Sycamore Platanus occidentalis Fair | tion Comments Uneven crown, vines, 10 degree lean | 105 24 White oak Quercus alba Good 106 24 Swamp white oak Quercus bicolor Good | 234 32 Red dak Quercus rabra Good 235 25 White oak Quercus alba Good 236 42 Tulip poplar Liriodendron tulipifera Good | 363 24 Tulip poplar Liriodendron tulipifera Fair twin @ 5', sparse canopy 364 27/ 25 Tulip poplar Liriodendron tulipifera Good |
| 2 28 Sycamore Platanus occidentalis Fair 3 28 White oak Quercus alba Good | Lots of vines, dead branches in crown, point taken 4' due S of tree | 107 34 Red oak Quercus rubra Good 108 34 White oak Quercus alba Fair Double trunk above DBH, dead branches in crown | 237 26 Tulip poplar <i>Liriodendron tulipifera</i> Good | 365 47 Tulip poplar Liriodendron tulipifera Good 366 25 Red oak Quercus rubra Good |
| 4 41 White oak Quercus alba Fair 5 26 Sycamore Platanus occidentalis Fair | 10 degree lean, dead branches, poison ivy Covered in vines, but otherwise looks good, point taken 1' E | 109 25 Red oak Quercus rubra Fair Strong lean in canopy 110 30 Red oak Quercus rubra Good | 238 24 River birch Betula nigra Poor Strong lean, on stream bank 239 31 Sycamore Platanus occidentalis Good | 367 42 Red maple Acer rubrum Poor dead branches, sparse canopy * 369 25 Mockernut hickory mostly dead 370 47 White oak Quercus alba Good |
| 6 27 Sycamore Platanus occidentalis Fair 7 29 Korean pine Pinus koraiensis Fair | Greater than 10 degree lean, half of roots exposed in stream | 111 38 Tulip poplar Liriodendron tulipifera Good 112 24 Tulip poplar Liriodendron tulipifera Good | 240 26 Sycamore Platanus occidentalis Poor Hollow trunk, crooked leader 241 32 Sycamore Platanus occidentalis Good | 371 27 White oak <i>Quercus alba</i> Good 371 30 White oak <i>Quercus alba</i> Good 372 30 White oak <i>Quercus alba</i> Good |
| 8 24 Tulip poplar Liriodendron tulipifera Good 10 40 Black walnut Juglans nigra Fair | Covered in vines, dead branches throughout | 113 25 Tulip poplar <i>Liriodendron tulipifera</i> Good 114 26 Tulip poplar <i>Liriodendron tulipifera</i> Good | * 242 35 Green ash Fraxinus pennsylvanica Fair Dead branches, vines 243 25 Tulip poplar Liriodendron tulipifera Good | 375 34 White oak Quercus alba Good 377 24 Korean pine Pinus koraiensis Excellent |
| 11 27 Tulip poplar Liriodendron tulipifera Good 12 47 Tulip poplar Liriodendron tulipifera Good | | 11524Tulip poplarLiriodendron tulipiferaFairUneven crown with broken branches11625Tulip poplarLiriodendron tulipiferaGood | 244 42 White oak Quercus alba Good 245 29 White oak Quercus alba Good | 378 33 Sycamore Platanus occidentalis Excellent 379 30 Sycamore Platanus occidentalis Excellent |
| 13 32 Red oak Quercus rubra Poor | Half of crown missing, Saveder has dead branches | 117 25 Tulip poplar Liriodendron tulipifera Good 118 28 Tulip poplar Liriodendron tulipifera Good | 246 34 White oak Quercus alba Good 247 30 Tulip poplar Liriodendron tulipifera Good | 380 32 Sycamore Platanus occidentalis Good 382 35 Sycamore Platanus occidentalis Excellent 383 33 Sycamore Platanus occidentalis Good |
| 1426Tulip poplarLiriodendron tulipiferaPoor1526Red mapleAcer rubrumGood | Uneven crown, covered in ivy, 10 degree lean | 119 28 Tulip poplar <i>Liriodendron tulipifera</i> Fair Uneven crown with strong lean 120 29/28 Tulip poplar <i>Liriodendron tulipifera</i> Good | 248 44 Red oak Quercus rubra Good 249 29 White oak Quercus alba Good | 384 29 Sycamore Platanus occidentalis Good * 385 33 Green ash Fraxinus pennsylvanica Good |
| 1628Tulip poplarLiriodendron tulipiferaGood1725CottonwoodPopulus deltoidesGood | | 121 26 Tulip poplar Liriodendron tulipifera Excellent 122 39 Sycamore Platanus occidentalis Fair Leaning strongly | 250 35 Tulip poplar <i>Liriodendron tulipifera</i> Fair Hollow trunk 251 37 Tulip poplar <i>Liriodendron tulipifera</i> Good | 386 28 Sycamore Platanus occidentalis Good 387 26 Sycamore Platanus occidentalis Good |
| 1845Tulip poplarLiriodendron tulipiferaGood1926Tulip poplarLiriodendron tulipiferaGood | | 123 25 Red maple Acer rubrum Good 124 32 Sycamore Platanus occidentalis Excellent | 252 32 Sycamore Platanus occidentalis Good 253 28 Sycamore Platanus occidentalis Fair Dead branches in crown | 388 29 Sycamore <i>Platanus occidentalis</i> Good 389 28 Korean pine <i>Pinus koraiensis</i> Good |
| 2029SycamorePlatanus occidentalisExcell2126Red mapleAcer rubrumGood | | 125 33 Tulip poplar Liriodendron tulipifera Good | 254 27 Eastern red cedar Juniperus virginiana Poor Hollow trunk, dead branches 255 25 Sycamore Platanus occidentalis Fair Uneven crown, broken branches | 390 24+ Black cherry Prunus serotina Poor covered in poison ivy, dead branches 391 39 Sycamore Platanus occidentalis Excellent |
| 22 25 Tulip poplar <i>Liriodendron tulipifera</i> Fair 23 41 White oak <i>Quercus alba</i> Excell | 1 trunk of double, uneven crown, 5 degree lean ent | 128 36 Tulip poplar Liriodendron tulipifera Good | 256 24/25 Sycamore Platanus occidentalis Fair Split 257 35 Sycamore Platanus occidentalis Good | 392 45 Sycamore Platanus occidentalis Fair broken branches, sparse canopy, vines 393 24 Tulip poplar Liriodendron tulipifera Good 394 32 Sycamore Platanus occidentalis Excellent |
| 24 44 White oak Quercus alba Poor | Poison ivy covered, 1 trunk dead | 130 26 Red maple Acer rubrum Good | 258 25 Sycamore Platanus occidentalis Poor Uneven crown, broken branches 259 26 Tulip Poplar Liriodendron tulipifera Good | 394 32 Sycamore Platanus occidentalis Excellent 395 35 Sycamore Platanus occidentalis Good 396 56 Sycamore Platanus occidentalis Good |
| 26 32 White oak Quercus alba Good | | 131 27 Tulip poplar Liriodendron tulipifera Fair Uneven crown with dead branches 132 35 Tulip poplar Liriodendron tulipifera Fair Vines, dead branches | 260 39 Tulip poplar Liriodendron tulipifera Good 261 33 White oak Quercus alba Good | 397 27 Tulip poplar Liriodendron tulipifera Excellent 398 24 Tulip poplar Liriodendron tulipifera Excellent |
| 2725SycamorePlatanus occidentalisGood2824SycamorePlatanus occidentalisGood | | 133 31 Red oak Quercus rubra Excellent 135 24 White oak Quercus alba Good | 262 33 Sycamore Platanus occidentalis Good 263 25 Tulip Poplar Liriodendron tulipifera Poor Split/hollow trunk, poison ivy | 399 28 Red oak <i>Quercus rubra</i> Good 400 28 Korean pine <i>Pinus koraiensis</i> Excellent |
| 2933White oakQuercus albaGood3033White oakQuercus albaGood | | 136 26 Red maple Acer rubrum Good 137 27 Tulip poplar Liriodendron tulipifera Good | 264 37 Tulip Poplar Liriodendron tulipifera Good 270 30 Silver maple Acer saccharinum Excellent | 401 39 Silver Maple Acer saccharinum Good 402 33 Box Elder Acer negundo Good 403 33 Shingle Oak Overcus imbrigaria Good |
| 31 33 White oak <i>Quercus alba</i> Fair 32 44 Tulip poplar <i>Liriodendron tulipifera</i> Good | | 13829Tulip poplarLiriodendron tulipiferaGood14025/26/27Red oakQuercus rubraFairTrunk damage, broken branches | 271 25 Silver maple Acer saccharinum Good | 403 33 Shingle Oak Quercus imbricaria Good 404 37 Sycamore Platanus occidentalis Poor 405 29 Red Maple Acer rubrum Poor |
| 33 35 Tulip poplar Liriodendron tulipifera Good 34 28 Tulip poplar Liriodendron tulipifera Excell | | 141 32 Tulip poplar Liriodendron tulipifera Fair Dead branches in crown 142 28 Tulip poplar Liriodendron tulipifera Good | 272 24 Sycamore Platanus occidentalis Good 273 26 Sycamore Platanus occidentalis Excellent 274 32 Silver maple Acer saccharinum Fair split into 3 @ 8'-1 part broken, covered in vines | 407 33 White oak Quercus alba Good |
| 35 24 Tulip poplar <i>Liriodendron tulipifera</i> Excell 36 40 Black walnut <i>Juglans nigra</i> Poor | | 143 24 Tulip poplar <i>Liriodendron tulipifera</i> Good 144 24 Tulip poplar <i>Liriodendron tulipifera</i> Fair Strong lean, on stream bank | 275 34.5/34 Osage orange Maclura pomifera Good | 409 39 White oak Quercus alba Good 410 31 Shingle Oak Quercus imbricaria Poor |
| 37 25 Sycamore Platanus occidentalis Fair | Covered in ivy | 146 26 Tulip poplar <i>Liriodendron tulipifera</i> Good 147 32 Tulip poplar <i>Liriodendron tulipifera</i> Good | 276 25 Tulip poplar Liriodendron tulipifera Good 277 25 Tulip poplar Liriodendron tulipifera Good | 411 37 Sycamore Platanus occidentalis Poor 412 26 Sycamore Platanus occidentalis Fair |
| 38 25 Sycamore Platanus occidentalis Fair 40 24 Red maple Acer rubrum Fair | Covered in ivy, strong lean | 148 27/33 Red oak Quercus rubra Excellent 149 30 White oak Quercus alba Fair Uneven crown, trunk damage | 278 31 Tulip poplar Liriodendron tulipifera Fair Topped in storm - no canopy 279 24 Tulip poplar Liriodendron tulipifera Poor Topped in storm - no canopy | 413 28 Sycamore Platanus occidentalis Fair 414 29 Sycamore Platanus occidentalis Good 416 40 White oak Quercus alba Good |
| 41 27 Scarlet oak Quercus coccineα Good 42 27 Scarlet oak Quercus coccineα Good | | 150 26 White oak Quercus alba Fair Trunk damage 151 26 White oak Quercus alba Good | 280 24 Tulip poplar Liriodendron tulipifera Poor Topped in storm -no canopy 281 30 Tulip poplar Liriodendron tulipifera Fair vines, small canopy, broken branches | * 417 62 Sycamore Platanus occidentalis Poor 418 24 Honey Locust Gleditsia tricanthos Poor |
| 43 25 Scarlet oak <i>Quercus coccinea</i> Fair 44 30 White oak <i>Quercus alba</i> Excell | | 152 33 Tulip poplar Liriodendron tulipifera Good 153 25 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown | - 282 35 Osage orange <i>Maclura pomifera</i> Fair broken branches, leaning 45 degrees 283 31 Tulip poplar <i>Liriodendron tulipifera</i> Good | 419 25 Tulip Poplar <i>Liriodendron tulipifera</i> Good 420 37 White oak <i>Quercus alba</i> Fair |
| 45 27 White oak Quercus alba Fair 46 26 Pignut hickory Carya glabra Fair | | 157 34 Red oak Quercus rubra Excellent 158 39 Red oak Quercus rubra Fair Dead branches, split trunk above DBH | - 284 30/ 26 Tulip poplar Liriodendron tulipifera Fair 285 40 Tulip poplar Liriodendron tulipifera Excellent | 421 24 Black Cherry Prunus serotina Fair Vine overgrowth 422 24 Tulip Poplar <i>Liriodendron tulipifera</i> Good |
| 47 25 White oak Quercus alba Good 49 33 White oak Quercus alba Good | | 159 29 White oak Quercus alba Fair Dead branches, split trunk above DBH | * 286 28 Pignut hickory Carya glabra Fair uneven canopy, broken branches 287 32 Tulip poplar Liriodendron tulipifera Fair uneven canopy, broken branches | 423 26 Tulip Poplar Liriodendron tulipifera Good 424 24 Mockernut hickory Carya tomentosa Good |
| 50 28 White oak Quercus alba Good 51 31 Tulip poplar Liriodendron tulipifera Good | | 160 35 Red oak Quercus rubra Good 161 31 Red oak Quercus rubra Poor Hollow base of trunk, broken branches | 288 30 Tulip poplar Liriodendron tulipifera Good 289 27 Sycamore Platanus occidentalis Excellent | 425 26 Tulip Poplar <i>Liriodendron tulipfera</i> Good 426 24 Northern Red Oak <i>Quercus rubra</i> Good 427 25 Tulip Poplar <i>Liriodendron tulipifera</i> Good |
| 52 25 Tulip poplar Liriodendron tulipifera Excell | ent | 162 41 Red oak Quercus rubra Fair Dead/broken branches in crown 163 34/35 Tulip poplar Liriodendron tulipifera Good | 290 24 Tulip poplar Liriodendron tulipifera Excellent 291 26 Tulip poplar Liriodendron tulipifera Excellent | 428 25 Northern Red Oak Quercus rubra Good 429 24 Northern Red Oak Quercus rubra Poor Lean, uneven canopy and branching |
| * 53 27 Pignut hickory Carya glabra Good 54 35 Korean pine Pinus koraiensis Excell | ent | 164 29 Tulip poplar <i>Liriodendron tulipifera</i> Fair Uneven crown, dead branches 165 26 White oak <i>Quercus alba</i> Excellent | 292 25 Tulip poplar <i>Liriodendron tulipifera</i> Good 293 24 Mockernut hickory Dead | 430 25 White Pine Pinus strobus Good 431 27 White Pine Pinus strobus Good |
| 5531Korean pinePinus koraiensisExcell5736Red oakQuercus rubraExcell | | 16627Red oakQuercus rubraGood16725Tulip poplarLiriodendron tulipiferaGood | 294 28 Tulip poplar <i>Liriodendron tulipifera</i> Good 295 28 Dead | 432 27 Tulip Poplar <i>Liriodendron tulipifera</i> Good 433 28 Silver Maple <i>Acer saccharinum</i> Good |
| 5827Korean pinePinus koraiensisGood5934Korean pinePinus koraiensisPoor | | 16827Tulip poplarLiriodendron tulipiferaFairDead/broken branches in crown16928Red oakQuercus rubraGood | 296 25 Tulip poplar <i>Liriodendron tulipifera</i> Good 297 29 Red maple <i>Acer rubrum</i> Excellent | 434 28 Tulip Poplar Liriodendron tulipifera Good 435 25 Tulip Poplar Liriodendron tulipifera Good 436 27 Tulip Poplar Liriodendron tulipifera Good |
| 60 25 Tulip poplar <i>Liriodendron tulipifera</i> Good 61 38 Southern red oak <i>Quercus falcata</i> Good | | 17029Tulip poplarLiriodendron tulipiferaPoorDead/broken branches in crown17127White oakQuercus albaGood | 298 25 Red maple Acer rubrum Good 299 24 Mockernut hickory Good | 437 24 Tulip Poplar Liriodentron tulipifera Good 438 24 White Pine Pinus strobus Good |
| 62 29 White oak Quercus alba Excell 63 33 Scarlet oak Quercus coccinea Excell | | 17227White oakQuercus albaPoorBroken/dead branches in crown17325Red oakQuercus rubraFairBroken branches in crown | 300 27 White oak Quercus alba Fair uneven canopy 301 25 White oak Quercus alba Good | 439 25 Tulip Poplar <i>Liriodendron tulipifera</i> Good 440 29 Black Walnut <i>Juglans nirga</i> Good |
| 64 31 Scarlet oak Quercus coccinea Excell * 65 32 Mockernut hickory Carya alba Excell | | 174 26 White oak <i>Quercus alba</i> Good 175 29 Tulip poplar <i>Liriodendron tulipifera</i> Good | 302 27 White oak Quercus alba Fair uneven canopy, smooth patch disease 303 31 White oak Quercus alba Good | 441 24 Black Walnut Juglans nigra Good * 442 49 Tulip Poplar Liriodendron tulipfera Good |
| 66 25 Mockernut hickory <i>Carya alba</i> Fair 69 27 Tulip poplar <i>Liriodendron tulipifera</i> Good | Lopsided crown, lean toward open water | 176 24 Tulip poplar <i>Liriodendron tulipifera</i> Good 177 24 Tulip poplar <i>Liriodendron tulipifera</i> Fair Uneven crown | 304 26 White oak Quercus alba Fair uneven canopy, dead branches 305 32 White oak Quercus alba Good | 443 25 Red Maple Acer rubrum Good 444 24 White Oak Quercus alba Good |
| * 70 27 Mockernut hickory Carya alba Excell | ent | 178 28 Red oak <i>Quercus rubra</i> Good 179 27 Red oak <i>Quercus rubra</i> Poor Dead branches, uneven crown | 306 28 Tulip poplar Liriodendron tulipifera Good 307 26 White oak Quercus alba Good | 445 25 Tulip Poplar <i>Liriodendron tulipifera</i> Good 446 24 Black Walnut <i>Juglans nigra</i> Good 447 25 Tulip Poplar <i>Liriodenton tulipifera</i> Good |
| 71 25 Tulip poplar <i>Liriodendron tulipifera</i> Good * 72 29 Pignut hickory <i>Carya glabra</i> Excell | | * 181 97 Red oak Quercus rubra Good 4 trunks above 4.5', larger than county & state champion 182 26 Tulip poplar Liriodendron tulipifera Good | 308 32 White oak Quercus alba Good | 448 24 Tulip Poplar <i>Liriodendron tulipifera</i> Good 449 25 Pin Oak <i>Quercus palustris</i> Good |
| 73 29 Red maple Acer rubrum Good 74 29 Red oak Quercus rubra Poor | | 183 26 White oak Quercus alba Good 184 28 Tulip poplar Liriodendron tulipifera Fair Vines, dead branches | 309 27 White oak Quercus alba Excellent 310 34 Tulip poplar Liriodendron tulipifera Good | 450 27 Tulip Poplar <i>Liriodendron tulipifera</i> Good 451 24 Black Oak <i>Quercus velutina</i> Good |
| 75 25 Tulip Poplar <i>Liriodendron tulipifera</i> Good 76 35 Red oak <i>Quercus rubra</i> Good | | 185 25 Tulip poplar Liriodendron tulipifera Good 186 26 Tulip poplar Liriodendron tulipifera Good | 311 29 White oak Quercus alba Good 312 25 Tulip poplar Liriodendron tulipifera Good | R502 26 Tulip Poplar Liriodendron tulipifera Good R503 25 White Oak Quercus alba Good R504 33 Tulip Poplar Liriodendron tulipifera Good |
| 77 26 Red oak Quercus rubrα Fair 78 37 Red oak Quercus rubrα Good | Dead branches in crown | 187 24 Tulip poplar <i>Liriodendron tulipifera</i> Good | | R506 26 Northern Red Oak Quercus rubra Good R538 28 Northern Red Oak Quercus rubra Good |
| 78 37 Red dak Quercus rubru Good 79 30 White oak Quercus alba Poor 80 26 Green ash Fraxinus pennsylvanica Good | | 188 31 Tulip poplar Liriodendron tulipifera Fair Uneven crown 189 26 Tulip poplar Liriodendron tulipifera Good | 315 26 Tulip poplar <i>Liriodendron tulipifera</i> Good 316 24 Tulip poplar <i>Liriodendron tulipifera</i> Good | R564 28 Green Ash Fraxinus pennsylvanica Good R565 36 Tulip Poplar Liriodendron tulipifera Good |
| 81 40 White oak Quercus alba Fair | Uneven crown, strong lean in crown | 190 25 Tulip poplar Liriodendron tulipifera Good 191 24 Tulip poplar Liriodendron tulipifera Good | 317 31 Red oak Quercus rubra Good 318 24 Tulip poplar Liriodendron tulipifera Poor topped in storm | R566 25 Tulip Poplar <i>Liriodendron tulipifera</i> Good R567 28 White Oak <i>Quercus alba</i> Good |
| 84 24 Tulip poplar Liriodendron tulipifera Good | | 192 25 Tulip poplar Liriodendron tulipifera Fair Uneven crown 193 38 Tulip poplar Liriodendron tulipifera Good | 319 24.5/ 24.5 Sycamore Platanus occidentalis Excellent 320 25 Red maple Acer rubrum Fair dead branches, diseased | R609 29 Red Maple Acerrubrum Good |
| the are let to the latest to the | | 194 31 Tulip poplar Liriodendron tulipifera Fair Uneven crown 195 32 Tulip poplar Liriodendron tulipifera Good | 321 26 Tulip poplar Liriodendron tulipifera Good 322 29 Tulip poplar Liriodendron tulipifera Excellent | A 15 Pine Pinus sp. Dead Dead will need to be removed for park user safety B 20 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety |
| 85 26 Tulip poplar <i>Liriodendron tulipifera</i> Good 86 28 Tulip poplar <i>Liriodendron tulipifera</i> Good | | 196 29 Tulip poplar <i>Liriodendron tulipifera</i> Good | 323 30 Tulip poplar Liriodendron tulipifera Good 324 27 Tulip poplar Liriodendron tulipifera Good | C 20 Tulip poplar Linodendron tulipfera Dead Dead will need to be removed for park user safety E 20 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety |
| | Broken branches in crown | 197 30 Tulip poplar Liriodendron tulipifera Good | | |
| 8628Tulip poplarLiriodendron tulipiferaGood8744White oakQuercus albaFair8833Red oakQuercus rubraGood | Broken branches in crown | 19730Tulip poplarLiriodendron tulipiferaGood19824Tulip poplarLiriodendron tulipiferaFairVines, uneven crown19928Tulip poplarLiriodendron tulipiferaFairBroken branches in crown | 325 24 Sycamore Platanus occidentalis Excellent 326 25 Tulip poplar Liriodendron tulipifera Poor sparse canopy, dead branches | F NA NA NA Dead Dead will need to be removed for park user safety G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CCIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% | Broken branches in crown DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 200 29 Tulip poplar Liriodendron tulipifera Good | 326 25 Tulip poplar <i>Liriodendron tulipifera</i> Poor sparse canopy, dead branches 327 24 Tulip poplar <i>Liriodendron tulipifera</i> Good | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 ISTER OF CHAMPION TREES, | Broken branches in crown DEVELOPER'S CERTIFICATE | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good | 326 25 Tulip poplar Liriodendron tulipifera Poor sparse canopy, dead branches 327 24 Tulip poplar Liriodendron tulipifera Good 328 26 Tulip poplar Liriodendron tulipifera Excellent 329 27 Red maple Acer rubrum Poor sparse canopy, dead branches | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 GISTER OF CHAMPION TREES, | DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012 , including financial bonding, forest planting, maintenance, and all other applicable agreements. | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Good 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Poor Hollow trunk, broken branches in crown | 326 25 Tulip poplar Liriodendron tulipifera Poor sparse canopy, dead branches 327 24 Tulip poplar Liriodendron tulipifera Good 328 26 Tulip poplar Liriodendron tulipifera Excellent 329 27 Red maple Acer rubrum Poor sparse canopy, dead branches 330 25 Tulip poplar Liriodendron tulipifera Good 331 28 Tulip poplar Liriodendron tulipifera Good | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety B 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety Dead Will need to be removed for park user safety Dead Will need to be removed for park user safety |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 ISTER OF CHAMPION TREES, ITGOMERY COUNTY, MARYLAND | Broken branches in crown DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012, including financial bonding, | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Poor Hollow trunk, broken branches in crown 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown | 326 25 Tulip poplar Liriodendron tulipifera Poor sparse canopy, dead branches 327 24 Tulip poplar Liriodendron tulipifera Good 328 26 Tulip poplar Liriodendron tulipifera Excellent 329 27 Red maple Acer rubrum Poor sparse canopy, dead branches 330 25 Tulip poplar Liriodendron tulipifera Good 331 28 Tulip poplar Liriodendron tulipifera Good 332 29 Tulip poplar Liriodendron tulipifera Good 333 24 Tulip poplar Liriodendron tulipifera Good | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety 80 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety "I, hereby certify that this Natural Resource Inventor accordance with the methodology described in the Trechnical Manual; adopted by Montgomery County (July |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CCIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 SISTER OF CHAMPION TREES, NTGOMERY COUNTY, MARYLAND | Broken branches in crown DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012, including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Poor Hollow trunk, broken branches in crown 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 207 29 Tulip poplar Liriodendron tulipifera Excellent 208 28 Tulip poplar Liriodendron tulipifera Good | 326 25 Tulip poplar Liriodendron tulipifera Poor sparse canopy, dead branches 327 24 Tulip poplar Liriodendron tulipifera Good 328 26 Tulip poplar Liriodendron tulipifera Excellent 329 27 Red maple Acer rubrum Poor sparse canopy, dead branches 330 25 Tulip poplar Liriodendron tulipifera Good 331 28 Tulip poplar Liriodendron tulipifera Good 332 29 Tulip poplar Liriodendron tulipifera Good 333 24 Tulip poplar Liriodendron tulipifera Good 334 29 Red oak Quercus rubra Good 335 27 Tulip poplar Liriodendron tulipifera Fair diseased | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety 80 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety "I, hereby certify that this Natural Resource Inventor accordance with the methodology described in the Tr Technical Manual; adopted by Montgomery County (July 1992), which was developed by the Natural Resources Division of the Maryland-National Capital Park and |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good ECIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 GISTER OF CHAMPION TREES, NTGOMERY COUNTY, MARYLAND www.gpinet.com | Broken branches in crown DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012, including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name Contact Person or Owner: MICHAEL ZELASKI, P.E. | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Good 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Good 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 207 29 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 208 28 Tulip poplar Liriodendron tulipifera Excellent 209 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good | 326 25 Tulip poplar Liriodendron tulipifera Poor sparse canopy, dead branches 327 24 Tulip poplar Liriodendron tulipifera Good 328 26 Tulip poplar Liriodendron tulipifera Excellent 329 27 Red maple Acer rubrum Poor sparse canopy, dead branches 330 25 Tulip poplar Liriodendron tulipifera Good 331 28 Tulip poplar Liriodendron tulipifera Good 332 29 Tulip poplar Liriodendron tulipifera Good 333 24 Tulip poplar Liriodendron tulipifera Good 334 29 Red oak Quercus rubra Good 335 27 Tulip poplar Liriodendron tulipifera Fair diseased 336 28 Tulip poplar Liriodendron tulipifera Excellent 337 28 Red oak Quercus rubra Excellent | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety 80 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety "I, hereby certify that this Natural Resource Inventor accordance with the methodology described in the Tr Technical Manual; adopted by Montgomery County (July |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 CISTER OF CHAMPION TREES, NTGOMERY COUNTY, MARYLAND www.gpinet.com pring Design Planning Construction Management aman-Pedersen, Inc. | DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012, including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name Contact Person or Owner: MICHAEL ZELASKI, P.E. Printed Name Address: 2425 REEDIE DRIVE, II+h FLR. WHEATON, MD 20902 | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Poor Hollow trunk, broken branches in crown 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 207 29 Tulip poplar Liriodendron tulipifera Excellent 208 28 Tulip poplar Liriodendron tulipifera Good 209 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 211 25 White oak Quercus alba Good | 326 25 Tulip poplar Liriodendron tulipifera Poor sparse canopy, dead branches | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety B0 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety I'l, hereby certify that this Natural Resource Inventor accordance with the methodology described in the Tr Technical Manual; adopted by Montgomery County (July 1992), which was developed by the Natural Resources Division of the Maryland-National Capital Park and Planning Commission (1989)." Signature: |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CIMEN TREES ARE BOLD REES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 STER OF CHAMPION TREES, TGOMERY COUNTY, MARYLAND www.gpinet.com ing Design Planning Construction Management man-Pedersen, Inc. Broken Land Parkway, Suite 500 pia, MD 21044 | Broken branches in crown DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012, including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name Contact Person or Owner: MICHAEL ZELASKI, P.E. Printed Name | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Good 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Poor Hollow trunk, broken branches in crown 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 207 29 Tulip poplar Liriodendron tulipifera Excellent 208 28 Tulip poplar Liriodendron tulipifera Good 209 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 211 25 White oak Quercus alba Good 212 25 White oak Quercus alba Good 213 35 White oak Quercus alba Good 214 26 Tulip poplar Liriodendron tulipifera Excellent 215 24 Tulip poplar Liriodendron tulipifera Excellent 216 Tulip poplar Liriodendron tulipifera Excellent 217 29 Tulip poplar Liriodendron tulipifera Excellent 218 209 Tulip poplar Liriodendron tulipifera Good 219 210 Tulip poplar Liriodendron tulipifera Excellent 210 Tulip poplar Liriodendron tulipifera Excellent 211 26 Tulip poplar Liriodendron tulipifera Excellent | 326 25 Tulip poplar Liriodendron tulipifera Good 327 24 Tulip poplar Liriodendron tulipifera Good 328 26 Tulip poplar Liriodendron tulipifera Excellent 329 27 Red maple Acer rubrum Poor sparse canopy, dead branches 330 25 Tulip poplar Liriodendron tulipifera Good 331 28 Tulip poplar Liriodendron tulipifera Good 332 29 Tulip poplar Liriodendron tulipifera Good 333 24 Tulip poplar Liriodendron tulipifera Good 334 29 Red oak Quercus rubra Good 335 27 Tulip poplar Liriodendron tulipifera Fair diseased 336 28 Tulip poplar Liriodendron tulipifera Excellent 337 28 Red oak Quercus rubra Excellent 338 28 Tulip poplar Liriodendron tulipifera Excellent 338 28 Tulip poplar Liriodendron tulipifera Excellent 339 33 Pignut hickory Carya glabra Good 340 28 Tulip poplar Liriodendron tulipifera Good | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety Bo 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety II, hereby certify that this Natural Resource Inventor accordance with the methodology described in the Trechnical Manual; adopted by Montgomery County (July 1992), which was developed by the Natural Resources Division of the Maryland-National Capital Park and Planning Commission (1989)." Signature: Brian Morgan, P.L.A. Greenman-Pedersen, Inc. |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 STER OF CHAMPION TREES, TGOMERY COUNTY, MARYLAND www.gpinet.com ing Design Planning Construction Management man-Pedersen, Inc. Broken Land Parkway, Suite 500 bia, MD 21044 | DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012 , including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name Contact Person or Owner: MICHAEL ZELASKI, P.E. Printed Name Address: 2425 REEDIE DRIVE, II+h FLR. WHEATON, MD 20902 Phone and Email: 301.495.2465 Michael.Zelaski@mon+gomeryparks.org | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Good 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Foor Hollow trunk, broken branches in crown 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 207 29 Tulip poplar Liriodendron tulipifera Excellent 208 28 Tulip poplar Liriodendron tulipifera Good 209 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 211 25 White oak Quercus alba Good 212 25 White oak Quercus alba Good 213 35 White oak Quercus alba Good 214 Culip poplar Liriodendron tulipifera Excellent Liriodendron tulipifera Excellent Good | 326 25 Tulip poplar Liriodendron tulipifera Good 327 24 Tulip poplar Liriodendron tulipifera Good 328 26 Tulip poplar Liriodendron tulipifera Excellent 329 27 Red maple Acer rubrum Poor sparse canopy, dead branches 330 25 Tulip poplar Liriodendron tulipifera Good 331 28 Tulip poplar Liriodendron tulipifera Good 332 29 Tulip poplar Liriodendron tulipifera Good 333 24 Tulip poplar Liriodendron tulipifera Good 334 29 Red oak Quercus rubra Good 335 27 Tulip poplar Liriodendron tulipifera Fair diseased 336 28 Tulip poplar Liriodendron tulipifera Excellent 337 28 Red oak Quercus rubra Excellent 338 28 Tulip poplar Liriodendron tulipifera Excellent 339 33 Pignut hickory Carya glabra Good 340 28 Tulip poplar Liriodendron tulipifera Good | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety 80 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety "I, hereby certify that this Natural Resource Inventor accordance with the methodology described in the Tr Technical Manual; adopted by Montgomery County (July 1992), which was developed by the Natural Resources Division of the Maryland-National Capital Park and Planning Commission (1989)." Signature: Brian Morgan, P.L.A. |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 STER OF CHAMPION TREES, TGOMERY COUNTY, MARYLAND www.gpinet.com ing Design Planning Construction Management man-Pedersen, Inc. Broken Land Parkway, Suite 500 bia, MD 21044 0.880.3055 | DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012 , including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name Contact Person or Owner: MICHAEL ZELASKI, P.E. Printed Name Address: 2425 REEDIE DRIVE, II+h FLR. WHEATON, MD 20902 Phone and Email: 301.495.2465 Michael.Zelaski@mon+gomeryparks.org Signature: Michael Zelaski Michael Zelaski | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Good 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Good 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Good 207 29 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 208 26 Tulip poplar Liriodendron tulipifera Excellent 209 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 211 25 White oak Quercus alba Good 212 25 White oak Quercus alba Good 213 35 White oak Quercus alba Good 214 26 Tulip poplar Liriodendron tulipifera Excellent 215 24 Tulip poplar Liriodendron tulipifera Excellent 216 27 White oak Quercus alba Good | 326 25 Tulip poplar Liriodendron tulipifera Good 328 26 Tulip poplar Liriodendron tulipifera Excellent 329 27 Red maple Acer rubrum Poor sparse canopy, dead branches 330 25 Tulip poplar Liriodendron tulipifera Good 331 28 Tulip poplar Liriodendron tulipifera Good 332 29 Tulip poplar Liriodendron tulipifera Good 332 29 Tulip poplar Liriodendron tulipifera Good 333 24 Tulip poplar Liriodendron tulipifera Good 334 29 Red oak Quercus rubra Good 335 27 Tulip poplar Liriodendron tulipifera Fair diseased 336 28 Tulip poplar Liriodendron tulipifera Excellent 337 28 Red oak Quercus rubra Excellent 338 28 Tulip poplar Liriodendron tulipifera Excellent 339 33 Pignut hickory Carya glabra Good 340 28 Tulip poplar Liriodendron tulipifera Good 341 38 White oak Quercus alba Good 343 35 White oak Quercus alba Good | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety I 15 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety B 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety WI, hereby certify that this Natural Resource Inventor accordance with the methodology described in the Tr Technical Manual; adopted by Montgomery County (July 1992), which was developed by the Natural Resources Division of the Maryland-National Capital Park and Planning Commission (1989)." Signature: Brian Morgan, P.L.A. Greenman- Pedersen, Inc. IIO00 Broken Land Parkway, Suite 500 Columbia, MD 21044 Professional Certification: North Branch Trail |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good ECIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 GISTER OF CHAMPION TREES, NTGOMERY COUNTY, MARYLAND | DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012 , including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name Contact Person or Owner: MICHAEL ZELASKI, P.E. Printed Name Address: 2425 REEDIE DRIVE, II+h FLR. WHEATON, MD 20902 Phone and Email: 301.495.2465 Michael.Zelaski@mon+gomeryparks.org Signature: Michael Zelaski Michael Zelaski | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Good 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Poor Hollow trunk, broken branches in crown 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 207 29 Tulip poplar Liriodendron tulipifera Excellent 208 28 Tulip poplar Liriodendron tulipifera Excellent 209 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 211 25 White oak Quercus alba Good 212 25 White oak Quercus alba Good 213 35 White oak Quercus alba Good 214 26 Tulip poplar Liriodendron tulipifera Excellent 215 24 Tulip poplar Liriodendron tulipifera Good 216 27 White oak Quercus alba Good 217 29 Tulip poplar Liriodendron tulipifera Good 218 27 White oak Quercus alba Good 219 29 Tulip poplar Liriodendron tulipifera Good 210 210 220 Tulip poplar Liriodendron tulipifera Good 211 220 Tulip poplar Liriodendron tulipifera Good 212 25 White oak Quercus alba Good 213 35 White oak Quercus alba Good 214 26 Tulip poplar Liriodendron tulipifera Good 215 27 White oak Quercus alba Good 216 27 White oak Quercus alba Good 217 29 Tulip poplar Liriodendron tulipifera Good | 326 25 Tulip poplar Liriodendron tulipifera Good 328 26 Tulip poplar Liriodendron tulipifera Excellent 329 27 Red maple Acer rubrum Poor sparse canopy, dead branches 330 25 Tulip poplar Liriodendron tulipifera Good 331 28 Tulip poplar Liriodendron tulipifera Good 332 29 Tulip poplar Liriodendron tulipifera Good 332 29 Tulip poplar Liriodendron tulipifera Good 333 24 Tulip poplar Liriodendron tulipifera Good 334 29 Red oak Quercus rubra Good 335 27 Tulip poplar Liriodendron tulipifera Fair diseased 336 28 Tulip poplar Liriodendron tulipifera Excellent 337 28 Red oak Quercus rubra Excellent 338 28 Tulip poplar Liriodendron tulipifera Excellent 339 33 Pignut hickory Carya glabra Good 340 28 Tulip poplar Liriodendron tulipifera Good 341 38 White oak Quercus alba Good 343 35 White oak Quercus alba Good | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety J 12 Oak Quercus sp. Dead Dead will need to be removed for park user safety K 20 Ash Fraxinus sp. Dead Should be removed for park user safety B0 12 Oak Quercus sp. Dead Should be removed for park user safety R 20 Ash Fraxinus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Should be removed for park user safety R 20 Oak Quercus sp. Dead Should be removed for park user safety R 20 Oak Quercus sp. Dead Should be removed for park user safety R 20 Oak Quercus sp. Dead Should be removed for park user safety R 20 Oak Quercus sp. Dead Should be removed for park user safety R 20 Oak Quercus sp. Dead Should be removed for park user safety R 20 Oak Quercus sp. Dead Should be removed for park user safety R 20 Oak Quercus sp. Dead Should be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dead Dead will need to be removed for park user safety R 20 Oak Quercus sp. Dea |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CCIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 GISTER OF CHAMPION TREES, NTGOMERY COUNTY, MARYLAND www.gpinet.com pring Design Planning Construction Management nman-Pedersen, Inc. D Broken Land Parkway, Suite 500 nbia, MD 21044 10.880.3055 | Broken branches in crown DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012 including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name Contact Person or Owner: MICHAEL ZELASKI, P.E. Printed Name Address: 2425 REEDIE DRIVE, II+h FLR. WHEATON, MD 20902 Phone and Email: 301.495.2465 Michael.Zelaski@mon+gomeryparks.org Signature: Wichael Zelaski REVIEW AND APPROVAL | 198 24 Tulip poplar Liriodendron tulipifera Fair Vines, uneven crown 199 28 Tulip poplar Liriodendron tulipifera Good 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Good 204 39 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Good 207 29 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 208 28 Tulip poplar Liriodendron tulipifera Excellent 208 28 Tulip poplar Liriodendron tulipifera Good 209 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 211 25 White oak Quercus alba Good 212 25 White oak Quercus alba Good 213 35 White oak Quercus alba Good 214 26 Tulip poplar Liriodendron tulipifera Excellent 215 24 Tulip poplar Liriodendron tulipifera Good 216 27 White oak Quercus alba Good 217 29 Tulip poplar Liriodendron tulipifera Good 218 219 Tulip poplar Liriodendron tulipifera Good 219 210 Liriodendron tulipifera Good 210 210 Tulip poplar Liriodendron tulipifera Good 211 29 Tulip poplar Liriodendron tulipifera Good 212 27 White oak Quercus alba Good 213 29 Tulip poplar Liriodendron tulipifera Good 214 26 Tulip poplar Liriodendron tulipifera Good 215 27 White oak Quercus alba Good 216 27 White oak Quercus alba Good 217 29 Tulip poplar Liriodendron tulipifera Good | 326 25 Tulip poplar Liriodendron tulipifera Good Good | G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 ISTER OF CHAMPION TREES, ITGOMERY COUNTY, MARYLAND www.gpinet.com ring Design Planning Construction Management man-Pedersen, Inc. Broken Land Parkway, Suite 500 abia, MD 21044 10.880.3055 | Broken branches in crown DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012 , including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name Contact Person or Owner: MICHAEL ZELASKI, P.E. Printed Name Address: 2425 REEDIE DRIVE, II+h FLR. WHEATON, MD 20902 Phone and Email: 301.495.2465 Michael.Zelaski@mon+gomeryparks.org Signature: Michael Zelaski REVIEW AND APPROVAL R | 198 24 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Good 205 32 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 206 32 Tulip poplar Liriodendron tulipifera Good 207 29 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 208 28 Tulip poplar Liriodendron tulipifera Good 209 24 Tulip poplar Liriodendron tulipifera Good 209 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 211 25 White oak Quercus alba Good 212 25 White oak Quercus alba Good 213 35 White oak Quercus alba Good 214 26 Tulip poplar Liriodendron tulipifera Excellent 215 24 Tulip poplar Liriodendron tulipifera Good 216 27 White oak Quercus alba Good 217 29 Tulip poplar Liriodendron tulipifera Good 219 29 Tulip poplar Liriodendron tulipifera Good 210 21 Tulip poplar Liriodendron tulipifera Good 211 29 Tulip poplar Liriodendron tulipifera Good 212 27 White oak Quercus alba Good 213 29 Tulip poplar Liriodendron tulipifera Good 214 20 Tulip poplar Liriodendron tulipifera Good 215 29 Tulip poplar Liriodendron tulipifera Good 216 27 White oak Quercus alba Good 217 29 Tulip poplar Liriodendron tulipifera Good 218 AND APPROVAL The Maryland And Plant Montgomery Counter | 326 25 Tulip poplar Liriodendron tulipifera Good Good | Professional Certification: Professional Certification: Intereby certify that these documents were prepared or approved by me, and that lam a duly licensed by me, and that lam a duly licensed in 15 Oak Parkinus sp. Dead Dead will need to be removed for park user safety Dead Dead will need to be removed for park user safety Dead Dead will need to be removed for park user safety Dead Dead will need to be removed for park user safety North Branch Trail PROJECT PROJ |
| 86 28 Tulip poplar Liriodendron tulipifera Good 87 44 White oak Quercus alba Fair 88 33 Red oak Quercus rubra Good CIMEN TREES ARE BOLD TREES GREATER THAN OR EQUAL TO 75% THE COUNTY CHAMPION AS LISTED IN 2011 ISTER OF CHAMPION TREES, ITGOMERY COUNTY, MARYLAND www.gpinet.com ring Design Planning Construction Management man-Pedersen, Inc. Broken Land Parkway, Suite 500 Ibia, MD 21044 10.880.3055 | Broken branches in crown DEVELOPER'S CERTIFICATE The undersigned agrees to execute all the features of Approved Final Forest Conservation Plan No. SC2019012, including financial bonding, forest planting, maintenance, and all other applicable agreements. Developer's Name: M-NCPPC, PPD Printed Company Name Contact Person or Owner: MICHAEL ZELASKI, P.E. Printed Name Address: 2425 REEDIE DRIVE, II+h FLR. WHEATON, MD 20902 Phone and Email: 301.495.2465 Michael.Zelaski@mon+gomeryparks.org Signature: Wichael Zelaski REVIEW AND APPROVAL R | 198 24 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 199 28 Tulip poplar Liriodendron tulipifera Good 200 29 Tulip poplar Liriodendron tulipifera Good 201 30 Tulip poplar Liriodendron tulipifera Good 202 28 Tulip poplar Liriodendron tulipifera Good 203 26 Tulip poplar Liriodendron tulipifera Fair Broken branches in crown 204 39 Tulip poplar Liriodendron tulipifera Good 205 32 Tulip poplar Liriodendron tulipifera Good 206 26 Tulip poplar Liriodendron tulipifera Good 207 29 Tulip poplar Liriodendron tulipifera Good 208 28 Tulip poplar Liriodendron tulipifera Good 209 24 Tulip poplar Liriodendron tulipifera Good 209 24 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 211 25 White oak Quercus alba Good 212 25 White oak Quercus alba Good 213 35 White oak Quercus alba Good 214 26 Tulip poplar Liriodendron tulipifera Excellent 215 24 Tulip poplar Liriodendron tulipifera Good 216 27 White oak Quercus alba Good 217 29 Tulip poplar Liriodendron tulipifera Good 218 20 Tulip poplar Liriodendron tulipifera Good 219 29 Tulip poplar Liriodendron tulipifera Good 210 24 Tulip poplar Liriodendron tulipifera Good 211 25 White oak Quercus alba Good 212 26 Tulip poplar Liriodendron tulipifera Good 213 35 White oak Quercus alba Good 214 26 Tulip poplar Liriodendron tulipifera Good 215 24 Tulip poplar Liriodendron tulipifera Good 216 27 White oak Quercus alba Good 217 29 Tulip poplar Liriodendron tulipifera Good 218 20 Tulip poplar Liriodendron tulipifera Good 219 20 Tulip poplar Liriodendron tulipifera Good 220 Tulip poplar Liriodendron tulipifera Good 221 24 Tulip poplar Liriodendron tulipifera Good 222 25 White oak Quercus alba Good 223 26 Tulip poplar Liriodendron tulipifera Good 224 26 Tulip poplar Liriodendron tulipifera Good 225 Tulip poplar Liriodendron tulipifera Good | 326 25 | Professional Certification: G NA Ash Fraxinus sp. Dead Dead will need to be removed for park user safety H 6 |