

GENERAL NOTES Area: 224,712 sqft or 5.16 Acres Zone: CR-3.0, C-2.5, R-2.5, H-100 CR-5.0, C-4.5, R-4.5, H-130 CRN-1.5, C-0.25, R-1.5, H-45 R-60 1. This site is located on Tax Map HQ51, HQ61 and WSSC grid 214NW03, and identified as Parcels P282, AND 0000 with Tax ID numbers 00966988, 01188512, 01027106, 01027378, 01026977, 01027015, 01027026, 01027004, and 01027458. Street addresses are 11250 Views Mill Road, 11200 Views Mill Road, 11227 East Avenue, 11225 East Avenue, 11223 East Avenue, East Avenue, East Avenue, 11217 East Avenue, and Upton Drive respectively. 2. Fieldwork for Boundary information, and Topography information – 2' contours, was conducted on 02/13/2019 by Charles P. Johnson & Associates. 3. Soils information was obtained from <u>www.websoilsurvey.ncrs.usda.gov</u> on January 23, 2020. 4. The site is located within the Lower Rock Creek watershed. 5. The site contains no Special Protection (SPA) or Primary Management (PMA) areas. 6. No Historic sites are located within or adjacent to this property. 7. No Rare or Threatened Species, Critical Habitats were observed on this property. 8. There are steep slopes located on-site. 9. The site contains no forest. There is a small portion of canopy from the properties along East Avenue 10. There are no significant views or vistas located on this site. 11. This site is located on tax map HQ51 AND HQ61. 12. This site is located on WSC 200 sheet 214NW03. 13. This site is located on ADC map grid F-11A. 14. This site is located in Election District 13. 15. This 16. WSS 17. Site 18. Lega

is site is to	cated in Liecth	Shi District 15.	
is site is lo	cated in the Lo	wer Rock Creek wa	tershed.
SSC service	e categories: S-	·1, W-1.	
e is to be s	serviced by pul	olic water and sewe	r systems.
gal descrip	otions		
rcel No.	Tax ID	Liber/Folio	Address
2	00966988	57142/231	11250 Views Mill Roa
00	01188512	10990/509	11200 Views Mill Roa
00	01027106	57142/231	11227 East Avenue
00	01027378	57142/231	11225 East Avenue
00	01026977	57142/231	11223 East Avenue
00	01027015	57142/231	East Avenue
00	01027026	57142/231	East Avenue
00	01027004	57142/231	11217 East Avenue
00	01027458	57142/231	Upton Drive



December 3, 2020

Mr. Michael Loe Charles P. Johnson & Associates, Inc. 1751 Elton Road

Suite 300 Silver Spring, MD 20903

ER# 2020.1746.mo

 RE: Environmental Review for Wheaton Gateway, Silver Spring: 11200 & 11250 Viers Mill Road, 11217-11250 East Avenue, 11201 Upton Drive, 2715 W. University Blvd., Montgomery County, Maryland.
Dear Mr. Loe:

The Wildlife and Heritage Service has determined that there are no official State or Federal records for listed plant or animal species within the delineated area shown on the map provided. As a result, we have no specific concerns regarding potential impacts or recommendations for protection measures at this time. Please let us know however if the limits of proposed disturbance or overall site boundaries change and we will provide you with an updated evaluation.

Thank you for allowing us the opportunity to review this project. If you should have any further questions regarding this information, please contact me at (410) 260-8573.

Sincerely, *fou* a. *by* Lori A. Byrne, Environmental Review Coordinator Wildlife and Heritage Service MD Dept. of Natural Resources

Tawes State Office Building – 580 Taylor Avenue – Annapolis, Maryland 21401 410-260-8DNR or toll free in Maryland 877-620-8DNR – *dnr.maryland.gov* – TTY Users Call via the Maryland Relay

SITE NARATIVE

This site is located on Tax Maps HQ51 and HQ61, and WSSC grid 214NW03. The site is identified as Parcels P282, and 0000. The site is approximately 5.16 acres in size. The site is bounded by Veirs Mill Road on the north, East Avenue on the south, Kensington Boulevard on the west, and Lot 16 Kensington View and Lot 2 Blk C Triangle Park to the east. The site contains commercial enterprises, except for a small portion in the southeast corner that is a grassy field with five specimen trees enclosed by a board on board fence. Field work for this NRI was conducted on October 22, 2020 by Michael Loe and Mark Staniford. DBH of tress were done using DTape. No Rare or Threatened Species, Critical Habitats were observed at this time. There are steep slopes on-site. The site is located within the Lower Rock watershed and has no PMAs or Special Protection areas located within the site. There are no Historical are located within or adjacent to the site. There are no cemeteries located within the site.

SOILS CHART							
SYMBOL	NAME	HYDRIC	SLOPE	SOIL GROUP	COMMENTS		
2C	Glenelg silt loam	No	8-15%	В	Well drained		
400	Urban land	No	N/A	D	N/A		
400	Urban land	NO	N/A		N/A		

		TREE LIST			
TAG NO	COMMON NAME	SCIENTIFIC NAME	DBH	CONDITION	COMMENTS
1	Hickory	Carya laciniosa	30	Good	
2	Red Maple	Acer rubrum	40	Good	
3	Bradford Pear	Pyrus communis	25	Poor	Split Limbs, Encumbered by wall
4	Cotton wood	Populus deltoides	32	Poor	Choked with vines
5	Red Maple	Acer rubrum	25	Fair	lvy, Dead Limbs
6	Red Maple	Acer rubrum	28	Good	
7	Red Oak	Quercus rubra	35	Fair	In ROW, Driveway apron damaged roots
8	Hickory	Carya laciniosa	40	Good	Off site
9	Silver Maple	Acer saccharinum	29	Good	Triple, within Kensington Blvd ROW

